


FITNESS CERTIFICATE OF SCHOOL BUILDING

1. Name of officer. - P T MINIMOL
 2. Name of school - Sree Narayana Public School Poothotta
 3. Location with Name of Education District/Sub district - Poothotta/ Ernakulam/Thripunithura
 4. Classification of building and size with year - Permanent structure
 of Construction of each building as specified - Class room Details attach additional sheet.


5. Period for which the Certificate is issued - 2020-2021
 6. Nature of Defect if any - Nil
 • 7.a) Foundation and basement - Framed structure
 b) Superstructure - Brick work in cement mortar
 c) Doors and Windows- Anjili wood and country wood
 d) wood work wrought and put up - Anjili wood
 e) Roof - R C C
 f) Flooring - Cement concrete flooring
 8. Any major defects modified which will render -
 The building unsafe in any manner- Nil
 9. Whether the Maintenance works have
 been done properly - Yes
 10. Whether the Structure is sound or not
 for Conducting classes- -sound under normal weather condition


Certified that the school was inspected by me on 29/09/2020/ and found to be fit to conduct classes for the period 2020-21 (Academic Year) under normal Weather conditions. The first Fitness is issued as per order No.EW3/330/2019 Dated 24/01/2020. The Structural Stability Certificate is Issued from Department of Civil Engineering Govt.Engineering College, Thrissur.

Place- Udayampereor
 Date- 29/09/2020.


 PRINCIPAL
 SREE NARAYANA PUBLIC SCHOOL
 POOTHOTTA




 29/09/2020
 Assistant Engineer
 LSGB Section
 Udayampereor


 MANAGER
 SREE NARAYANA PUBLIC SCHOOL,
 POOTHOTTA



In col4 of the Application for fitness certificate

-	G F-1.	class room -	18x6.2x6.2x3.70
-	2.	lab-1x6.20x9.40x3.70	
	3.	staff room -1x6.2x6.2x3.70	
		" -1x6.20x3.00x3.70	
	4.	office 1x3.0x3.75x3.70	
		Do 1x3.00x3.30x3.70	
	5.	manager 1x3.00x2.3x3.70	
	6.	Vice.princi 1x3.00x2.30x3.70	
	7.	store room 1x4.65x2.20x3.70	
	8.	Toilet Block. 1x6.20x4.40x3.70	
		Toilet Block. 1x6.20x2.80x3.70	
	9.	Visitors room 1x6.15x6.00x3.70	

In col4 of the Application for fitness certificate

-	F F-	1.	class room -	16x6.2x6.2x3.70
-		2.	lab- -	1x6.2x12.0x3.70
		3.	Library -	1x15.00x6.2x3.70
		4.	Room -	1x6.20x3.00x3.70
		5.	computer Lab	1x7.15x8.80x3.70
			Do	1x6.20x6.20x3.70
		6.	Principal Room-	1x6.30x5.00x3.70
		7.	Toilet Block.	1x6.20x4.40x3.70
			Toilet Block.	1x6.20x2.80x3.70

In column 4 of the application for Fitness certificate

-	S F -1.	class room -	17x6.2x6.2x3.70
			1x6.20x9.40x3.70
			1x7.15x8.80x3.70
			1x8.60x6.20x3.70
	2.	Lab	1x12.00x6.20x3.70
	3.	Toilet Block.	1x6.20x4.40x3.70
		Toilet Block.	1x6.20x2.80x3.70

Certified that the school was inspected by me on 29/09 / 2020 / and found to be fit to conduct classes for the period 2020-21 (Academic Year) under normal Weather conditions .The first Fitness is issued as per order No.EW3/330/2019 Dated 24/01/2020 .The Structural Stability Certificate is Issued from Department of Civil Engineering Govt.Engineering College ,Thrissur.

Place- Udayamperoor
Date- 29/09/2020.

Jaltheetha
PRINCIPAL
SREE NARAYANA PUBLIC SCHOOL
POOTHOTTA



Udayamperoor
29/9/2020
Assistant Engineer
L&SD Section
Udayamperoor

[Signature]
MANAGER
SREE NARAYANA PUBLIC SCHOOL
POOTHOTTA

